

FIG. 1





FIG. 2






**FIG. 3**


FIG. 4



**FIG. 5**




**FIG. 6**




**FIG. 7**

TEMPORARY  
NOTIFICATION SCREEN




**FIG. 8**

INVESTIGATION  
TABLE SCREEN




**FIG. 9**

Nth INVESTIGATION  
TABLE SCREEN



**FIG. 10**

USER MAINTENANCE  
MANUAL SCREEN



**FIG. 11**

ENDING SCREEN

307

NOTICE OF USER MAINTENANCE  
RESULT

- ☐ IMPROVED
- ☐ NOT IMPROVED
  - ☐ INVESTIGATE AGAIN
  - ☐ REQUEST CALLING OUT  
SERVICEMAN

TRANSMIT

307a

307b

Detailed description: The diagram shows a rounded rectangular frame labeled 307. Inside the frame is a rectangular box containing the text 'NOTICE OF USER MAINTENANCE RESULT'. Below this text are four checkboxes. The first two are 'IMPROVED' and 'NOT IMPROVED'. The 'NOT IMPROVED' checkbox is followed by a sub-list containing 'INVESTIGATE AGAIN' and 'REQUEST CALLING OUT SERVICEMAN'. At the bottom right of the inner box is a shaded rectangular button labeled 'TRANSMIT'. To the right of the main frame, there are two labels: '307a' pointing to the right edge of the frame and '307b' pointing to the 'TRANSMIT' button.



**FIG. 12**

PROBLEM

PROBLEM  
NOTIFICATION

401

CONCERNING SHEET

SHEET FOLDED

SLANTED PRINT

DOUBLE FEED

JAM

CONCERNING IMAGE QUALITY

SMEARED WITH BLACK

BLOB

WHITE OUT

BLURRED

PROBLEM DEGREE

IMPOSSIBLE TO USE

TERRIBLE

BARELY ACCEPTABLE

ACCEPTABLE

SEND


SEND

BACK TO PREVIOUS SCREEN


STOP

402

FIG. 13



**FIG. 14**



**FIG. 15**

